



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-200

Date: June, 2016

TECHNICAL

Subject: Power Steering Reduced Message and/or Malfunction Light (MIL) Illuminated

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu (VIN Z)	2016	2016				

Involved Region or Country	North America, Israel
Condition	<p>Some customers may comment on the following conditions:</p> <ul style="list-style-type: none"> • Power Steering Reduced message was on. • Malfunction Indicator Lamp (MIL) illuminated. <p>The Technician may find one or more of the following DTCs set:</p> <ul style="list-style-type: none"> • U0415 • U0420

Correction

If the Power Steering Reduced - Drive With Care message is on and/or MIL is illuminated, the Power Steering Control Module needs to be reprogrammed.

Updated software is available for the Power Steering Control Module.

Service Procedure

Refer to *Power Steering Control Module Programming and Setup* in SI.

Warranty Information

Labor Operation	Description	Labor Time
2810625	Power Steering Control Module Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION