



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-207

Date: June, 2016

TECHNICAL

Subject: Buzzing Noise Heard and/or Vibration Felt in Shifter Assembly and/or Shifter Console During Aggressive Driving and Parking Maneuvers After Vehicle has Warmed Up

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT6	2016	2016				

Involved Region or Country	North America and N.A. Export Regions
Condition	The customer may comment on a buzzing noise and/or a vibration felt in the shifter assembly and/or shifter console during aggressive driving or during parking after the vehicle has warmed up.
Cause	This may be caused by a vibration/frequency traveling through the transmission shift cable into the console area where the cable is attached to the shifter.

Correction

If the shifter cable has been found to be the cause of the customer concern, the shifter cable must be replaced.

Service Procedure

Refer to *Range Selector Lever Cable Replacement* in SI.

Parts Information

Description	Part Number	Qty
CABLE, A/Trans Range Sel Lvr	23349970	1

Warranty Information

Labor Operation	Description	Labor Time
8460370	Range Selector Lever Cable Replacement	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION