



GROUP <b>CHA</b>	MODEL <b>2014MY Sorento (XMa)</b>
NUMBER <b>070</b>	DATE <b>August 2016</b>

## TECHNICAL SERVICE BULLETIN

**SUBJECT: TPMS SENSOR INOPERATIVE**

This bulletin provides the procedure to replace all Tire Pressure Monitoring System (TPMS) sensors on 2014MY Sorento (XMa) vehicles, when any of the TPMS sensors are confirmed inoperative.

To enhance customer satisfaction, this bulletin outlines the replacement of the TPMS sensors on all 4 wheels to resolve the concern, even if only one sensor is affected.



**File Under: Service Campaign**

---

**Circulate To:**     **General Manager**     **Service Manager**     **Parts Manager**  
 **Service Advisors**     **Technicians**     **Body Shop Manager**     **Fleet Repair**

SUBJECT:

## TPMS SENSOR INOPERATIVE


**Service Procedure:**

1. Replace all TPMS sensors by referring to the "Suspension System→ Tire Pressure Monitoring System→ TPMS Sensor→ Repair procedures" chapter in the applicable Workshop Manual on KGIS.
2. Verify that replacing the TPMS sensors resolved the problem.

## AFFECTED VEHICLE RANGE:

Model	Production Date Range
Sorento (XMa)	12/17/12~02/10/14

## REQUIRED PART:

Part Name	Part Number	Figure
TPMS Valve Assembly	52933 2M550	

## WARRANTY INFORMATION:

Claim Type	Causal P/N	Qty.	N Code	C Code	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
W	52933 2M550	4	I3O	ZZ4	TPMS Valve Assembly R&R	52933F01	1.0 M/H	52933 2M550	4