

Software Update (1.20.1): Boom! Box 4.3/6.5GT/6.5 CVO GT

Improvements

- Zoom out levels have been increased to allow for viewing of longer routes.
- Azerbaijan Map has been added to the ROW map database.
- The heading directional display will now operate as a traditional compass with the top representing the direction ahead and the rotating needle shall point to the direction of North.
- The disclaimer or "Accept" screen will now auto advance after 15 seconds.

Added Features

- Autozoom can be configured in Navigation Setup Appearance menu.
- There are four separate levels based on what zoom level the map will return to after the autozoom.
 - i. OFF – Autozoom is disabled (default)
 - ii. NEAR – It will return to the tightest scale.
 - iii. NORMAL – It will return to the middle scale.
 - iv. FAR – It will return to the widest scale.
- Vehicle Information screen will display "OK" or "Check Oil" for oil pressure on MY17 models.

Fixes

- Endless authentication during navigation updates
- Radio starting in clock/off screen display
- Access to tire pressure info on applicable models while in clock/off screen display
- XM stuck in "retrieving data" screen
- Score updates through XM are not automatic after adding team to favorites
- Voice recognition feature for "search by channel name"
- Bluetooth Audio stuck in fast forward when held between songs
- Quick press of "back" in genre search results in empty list
- Seek through presets of multiple USB devices pauses media
- Going from XM to audio menu back to XM removes button text
- Selecting "back" from POI location search defaults to "Near Location"
- Quick key cycle with MTP device results in screen staying off
- Reduced time to index device with large number of songs
- 100% Precipitation displayed as "10%" in weather screen
- Map response improvement at elevated zoom levels
- GEO coordinate entry in some languages
- Navigation prompts "Repeat" button functionality addressed.
- Tuner scan stops after 2 times around band
- Radio waking up while in clock screen

Software Update (1.20.1.1): Boom! Box 6.5GT/6.5 CVO GT (HDI and ROW only)

Navigation Fixes

- Correction to RDS traffic functionality (HDI and ROW units).

Software Update (1.20.2): Boom! Box 4.3/6.5GT/6.5 CVO GT

Improvements

- Support for quarterly dealer database updates and database version screen.
- Switch to call screen when call initiated from phone.
- Headset sidetones added for CB.
- Prompt user to transfer active call to device at key off.
- Default zoom level set for Maneuvers.

Added Features

- Siri functionality has been added. Hold Voice Recognition button for 5 seconds to activate.
- Added media browsing over Bluetooth for iPhone.
- New feature to allow searching for another address while still having an active route.

Fixes

- Allow Nav and Dealer USB update prior to Navigation Loading.
- Post Code entry for HDI and ROW radios has been re-enabled.
- Media pause after fast forward.
- Activation code issue when USB drive is removed and reinserted.
- Navigation data fields no longer overlap next turn during recalculation.
- Japan radio shows Setup button twice.
- Weather map zoom level persistence.
- Passenger Intercom volume shows "off" when driver adjusts.
- Prevent import of Nav destinations with incomplete data.
- Media remains paused after multiple rapid prompts.
- Roadway icons overlap in traffic list.
- Improved indexing time for USB devices with large numbers of media files.
- Bluetooth connection persistence.
- Performance and stability enhancements.