

Technical Service Bulletin

17 Message "Oil level sensor: oil change necessary. Please contact Service." in instrument cluster

17 16 79 2045581/2 December 23, 2016. Supersedes Technical Service Bulletin Group 17 number 16-78 dated October 11, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3 e-tron	2016 - 2017	All	e-tron

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Technical Background</i> (Updated Tip) Revised <i>Service</i> (Updated procedure) Revised <i>Warranty</i> (Added maintenance statement)
1	10/11/2016	Initial publication

Customer complaint:

- The message "Oil level sensor: oil change necessary. Please contact service" appears too early for due service.

Workshop Findings:

- The customer statement can be reproduced.
- No fault code for the oil level sensor is logged.

Technical Background

Oil level too high because the oil was extracted at the last oil change service contrary to the instructions in the maintenance documents. The oil has to be drained.



Tip:

At the last oil change/service too much oil was put into the vehicle.



Technical Service Bulletin

Production Solution

Not applicable.

Service

A replacement of the oil level sensor does not fix the problem.

Correct the oil level as described in the maintenance documents.

Warranty

The replacement of the oil level sensor for the above conditions is not covered under warranty.

If the complaint occurred because maintenance guidelines were ignored, an accounting on the manufacturer/importer is not possible.

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2045581) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2016 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.