

© 2016 Mazda Motor of America, Inc.

<b>Subject:</b> <b>INCORRECT COLOR REAR DOOR TRIM GRIP COVER(S) INSTALLED</b>	<b>Bulletin No:</b> 09-045/16
	<b>Last Issued:</b> 07/29/2016


## APPLICABLE MODEL(S)/VINS

2016 CX-9 vehicles (equipped with Beige interior) with VINs lower than JM3KE\*\*\*\*\*111471 (produced before June 20, 2016)

## DESCRIPTION

Some vehicles equipped with “Beige” interior, may have “Black” rear door trim grip cover(s) (A) installed in their vehicle by mistake. The correct color of the grip covers is “Beige” to match the color of the vehicle interior.

This concern was caused by erroneous assembly instructions at the factory, which has since been corrected.



Customers having this concern should have their vehicle repaired using the following repair procedure.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by “do-it-yourselfers.” Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



## REPAIR PROCEDURE

1. Verify the customer concern.
  - If the rear door trim grip cover(s) in the customers vehicle are found to be Black, replace them with Beige parts according to the following procedure.

**NOTE:** The illustration below shows the left side rear door; The right side uses the same procedure.

2. Gently remove the rear door trim grip cover (A) in the direction of the arrows shown below.

**NOTE:** Detach and remove the clips and tabs in order (1) and (2) as shown below.



3. Install the correct color part(s) in the reverse order of removal.
4. Verify the repair.

## PART(S) INFORMATION

Part Number	Description	Qty.	Color
TK79-68-D62A-2A	Rear door trim grip cover (R )	1	Beige / Right
TK79-68-D82A-2A	Rear door trim grip cover (L )	1	Beige / Left

## WARRANTY INFORMATION

**NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	46
Damage Code	9N
Part Number Main Cause	TK79-68-D62A-2A - Door trim grip cover (R)
Quantity	1
Related Part Number	TK79-68-D82A-2A - Door trim grip cover (L)
Quantity	1
Operation Number / Labor Hours:	XXM5AXRX / 0.2 Hrs.