

SSM 45960	Some 2016 F-650/750 vehicles equipped with a 6.7L Diesel engine may exhibit incorrect diesel exhaust fluid gauge indication. If there are no diesel exhaust fluid level related Diagnostic Trouble Codes (DTCs) in the PCM or the IPC, run the Integrated Diagnostic System (IDS) Selective Catalytic Reduction (SCR) System Refill Activation routine. If performing IDS SCR System Refill Activation routine does not resolve the concern, do not attempt further repairs. Engineering is investigating. Monitor OASIS for future updates.
--------------	--