SSM 45980	2017 F-250 - F-550 with the optional Lane Keeping System may display →Lane Keeping System Malfunction→ in the Instrument cluster with no DTC→s present. Engineering is aware of this concern and will release software via IDS to update the Image Processing Module →A→ (IPMA)when available. No repair attempts should be made at this time. Monitor OASIS for updates.
--------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------