

SSM 46011	Some 2015-2017 Focus/C-MAX/Escape vehicles equipped with One touch up feature. The 2016-2017 workshop manual Section 501-11 was updated 8/2016 with revised diagnostics, the 2015 WSM updates will follow later. Refer to the 2016-2017 WSM revised diagnostics for any of the following concerns: One-touch up feature is inoperative, window door glass does not travel fully to either open/Closed position, and window bounces back concerns. At the beginning of Pinpoint test E, Carry out the initialization procedure on the suspect power window, before continuing the pinpoint test. REFER to: Power Door Window Initialization - Vehicles With: One-Touch Open and Close Front Windows (501-11 Glass, Frames and Mechanisms, General Procedures).
--------------	---