

## Title

2016 CX-9 - DRIVEABILITY CONCERNS DUE TO LOW FUEL LEVEL

## Content

Some vehicles may exhibit a lack of power and/or misfires during PDI. This may be due to a low fuel level in the fuel tank. Verify there is at least a ¼ tank of fuel in the tank. If not, fill to ¼ tank, start the engine and drive the vehicle for a minimum of 1 mile to purge any air remaining in the fuel system, then re-test.

NOTE: Fill the fuel tank with adequate fuel (¼ tank or more) prior to driving the vehicle to exit "Delivery Mode". Continuing to drive the vehicle with very low fuel levels may cause damage to the fuel pump.

- If the concern is resolved by adding fuel, DO NOT contact the Technical Assistance Hotline or create a PQM alert.
- If the concern is NOT resolved by adding fuel, contact the Technical Assistance Hotline.