

---

<b>Reference</b>	SSM72893
<b>Models</b>	F-PACE / X761
<b>Title</b>	Rear door alignment (F Pace only)
<b>Category</b>	Body
<b>Last modified</b>	26-Jul-2016 00:00:00
<b>Symptom</b>	108000 Ext. Trim/Accessories

---

**Content****Issue**

Rear door alignment not as expected.

**Cause**

Variation in the setting procedure in the manufacturing process.

**Action**

The workshop manual has been updated, and now includes the rear door alignment processes for F Pace.

Should a vehicle be presented with the issue noted above, realign the rear door as detailed in Topix – Workshop Manual – Section 501-03 – General Procedures – Rear Door Alignment.