
Reference	SSM72902
Models	XJ / X351
Title	X351 Transit Relay Removal (System Initialisation)
Category	Electrical
Last modified	28-Jul-2016 00:00:00
Symptom	203000 Basic Electrical

Content**Issue**

Electric Window, Sun / Moon roof, Rear side window blinds, inoperative or not functioning correctly after PDI.

Cause

Systems not being re initialised after PDI transit relay removal.

Action

Electric Window, Sun / Moon roof, Rear side window blinds all require re initialisation after the transit relay is removed.

For further information please refer to

- Workshop Manual Section 501-11 in TOPIx
- PDI-23914 - PDI Manual XJ Range (Preliminary section) in TOPIx
- SSM72201 - X351 side rear window electronic sunblind (LWB only)
- SSM72694 - X351 Rear side window sunblind jams or fails to operate