

SSM  
46260

Some 2015-2017 F-150 SuperCab vehicles may exhibit inoperative rear door lower latches during freezing temperatures. The rear door lower latches have been revised to include a water shield and the parts catalog has been updated to show the new numbers. Replace the rear door lower latches, refer to Workshop Manual (WSM), Section 501-14. For claiming, use causal part 18264A00 and applicable labor operations in section 12 of the service labor time standards (SLTS) manual.