

SSM
46278

Some 2017 MKX vehicles equipped with Lincoln drive control and built on or before 2-Dec-2016 may exhibit a missing Lincoln drive control menu in the instrument cluster message center. To correct the condition, update the cluster as-built configuration using Integrated Diagnostic System (IDS) version 103.01 or higher. Make sure you are connected to the internet when downloading the updated as-built data. For claiming, use causal part 10849 and applicable labor operation(s) in Section 10 of the Service Labor Time Standards (SLTS) Manual.