



Service Bulletin

INFORMATION

Subject: Engineering Information – Bang or Loud Noise with No Forward (Drive) or Reverse Ranges

Models: 2015-2016 Cadillac Escalade Models
2016 Cadillac ATS, ATS-V, CTS, CTS-V Models
2015-2016 Chevrolet Silverado
2016 Chevrolet Camaro
2015-2016 GMC Sierra, Yukon Models
Equipped with 8 Speed Automatic Transmission 8L90 (RPO M5U) or 8L45 (RPOs M5T, M5N)

This PI has been revised to end the need for information from the field. Please discard PIE0350B.

If you encounter a vehicle with this concern, please refer to SI diagnostics.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION