

Technical Service Bulletin

94 Dimmer cap missing from headlight switch

94 16 81 2031378/3 September 14, 2016. Supersedes Technical Service Bulletin Group 94 number 13-26 dated August 1, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6	2011 - 2018	All	Light Switch with Dimmer Knob
A7	2011 - 2018	All	Light Switch with Dimmer Knob

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header data (added model years)
1	10/25/2012	Initial publication

Cap on dimmer knob (light switch) has fallen off and cannot be found (Figure 1).



Figure 1. Dimmer knob on main light switch



Technical Service Bulletin

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

Replace missing cap. Do *not* replace the main light switch. Switches replaced for this condition will be charged back.

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	9405		
Damage Code:	0010		
Labor Operations:	Replace Dimmer cap	9405 1999	10 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	No allowance	0 TU



Technical Service Bulletin

	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2031378/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
4G0941158B	Cap for dimmer switch	1

Additional Information

All parts and service references provided in this TSB (2031378) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2016 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.