



Technical Service Bulletin

94 Headlight switch pressed in

94 16 82 2017566/6 September 16, 2016. Supersedes Technical Service Bulletin Group 94 number 15-66 dated April 17, 2015 for reasons listed below.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|--------------|-------------|-----------|----------------------------|
| A3 | 2013 - 2018 | All | Headlight Switch Knob |
| A4 | 2008 – 2018 | All | Headlight Switch Knob |
| A5 | 2008 – 2016 | All | Headlight Switch Knob |
| A5 Cabriolet | 2008 – 2016 | All | Headlight Switch Knob |
| A6 | 2011 – 2018 | All | Headlight Switch Knob |
| A7 | 2011 – 2018 | All | Headlight Switch Knob |
| Q7 | 2015 – 2018 | All | Headlight Switch Knob |
| TT | 2015 - 2018 | All | Headlight Switch Knob |

Condition

| REVISION HISTORY | | |
|------------------|-----------|--|
| Revision | Date | Purpose |
| 6 | - | Revised header data (Added models and model years) |
| 5 | 4/17/2015 | Revised header data (Added models and model years) Revised <i>Technical Background</i> (Added photos) |
| 4 | 3/29/2013 | Revised header data (Added model years and A6/A7) |

The headlight switch knob is pressed in, but the switch functions correctly.

Technical Service Bulletin

Technical Background

The headlight switch knob was designed with a normal position and a pushed-in position (Figure 1, Figure 2, and Figure 3). This feature was designed to avoid injuries during a collision.



Figure 1. B8 headlight switch knob pushed in (left) and in normal position (right).



Figure 2. A3 headlight switch knob pushed in (left) and in normal position (right).

Technical Service Bulletin



Figure 3. A6 and A7 headlight switch knob pushed in (left) and in normal position (right).

Production Solution

Not applicable.

Service

1. Pull out the knob and return it to the original position.
2. Explain the *Technical Background* to the customer.

Warranty

This TSB is informational only and not applicable to any Audi warranty.



Technical Service Bulletin

Additional Information

All parts and service references provided in this TSB (2017566) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2016 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.