Reference	SSM73025
Models	F-PACE / X761 XE / X760 XF / X260 XJ / X351
Title	InControl Touch Pro problems with Global Postioning System (GPS)
Category	Electrical
Last modified	24-Oct-2016 00:00:00
Symptom	207000 Entertainment Systems
Content	<ul> <li>Issue Customer complaint of</li> <li>No GPS signal.</li> <li>No update on current vehicle position on the display.</li> <li>No update to the time displayed.</li> <li>China only might state that the GPS page says the GPS signal is invalid.</li> </ul> Cause Memory updates can become corrupted when data is being stored. Action: Update the Information Master Controller(IMC) using DVD147.03 or later. Do not replace the IMC for this issue.
	<ul> <li>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</li> <li>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</li> <li>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</li> <li>5 = Excellent – All required information provided to resolve the customer concern.</li> </ul>