



Service Bulletin

PRELIMINARY INFORMATION

Subject: Advanced Park Assist Parking Maneuvers Inaccurate

Models: 2016 Cadillac CTS-V
Built prior to VIN G0140569

This PI was superseded to update Recommendation/Instructions. Please discard PIC6167.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

During a parallel parking maneuver, the vehicle will park between cars but only slightly into the spot. Final parking position will be over half way into the roadway. During a perpendicular parking maneuver, the system may indicate an open parking space but try to park next to the open spot (where a car may already exist).

Recommendation/Instructions

Perform the following steps to resolve this issue:

1. Program the K41 Park Assist Control Module using SPS Programming.
2. Select K41 Park Assist Control Module Configuration and follow on screen instruction.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810375	Parking Assist Control Module Reprogramming with SPS	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION