

SSM
46216

Some 2016 F-150 vehicles equipped with a floor shifter may exhibit a difficult to remove ignition key prior to PDI. Before initiating diagnosis, remove the protective shipping cover from the floor shifter and reevaluate. If the concern is not resolved, refer to Workshop Manual (WSM), Section 307-05 for normal diagnosis.