



Service Bulletin 530

Issue 1 - 04.2016

Subject: Brake Hose Retaining Clip Removal				
Bulletin Number	Models Affected	VIN Range		Markets Affected
530	Street Twin	Up to	753869	All Markets
	Bonneville T120	Up to	753869	All Markets
	Bonneville T120 Black	Up to	753869	All Markets

Background Information

Internal investigations have identified a need to remove one of the front brake hose clips to prevent potential scratching of the front mudguard.

Dealers are requested to remove and discard the front brake hose clip as described.

Dealers must also inspect the front mudguard and brake hose for any damage. If the front mudguard or brake hose are damaged, dealers are requested to contact Triumph Warranty Technical Support for repair instructions.

Customer Contact Instructions

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

Identification of Affected Motorcycles

Street Twin, Bonneville T120, Bonneville T120 Black models listed in the VIN ranges above.

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- The modified motorcycles can be identified by checking the 'Outstanding Service Bulletins' on Warranty Online.

Warranty Claim Instructions

Bulletin Number	Fault Code	Repair Code	Description	Repair Time Allowance
530	023005930	99530	Remove brake hose retaining clip	0.01 hours

Genuine Parts Information

Bulletin Number	Part Number	Description	Quantity
530	Not applicable	Not applicable	Not applicable

Parts Ordering Instructions
Genuine Parts Return Instructions

Not applicable
Not applicable

Other Instructions

Before returning the motorcycle to the customer, download the latest calibration to the engine control module using the current version of the Triumph diagnostic software.

Once completed, please mark the Service Record Book that the requirements of this bulletin have been complied with.


Remove the Brake Hose Retaining Clip Procedure

Remove the lower front brake hose clip following the procedure described below. If the front mudguard or front brake hose is damaged, contact Triumph Warranty Technical Support for repair instructions.

Warning

Before starting work, ensure the motorcycle is stabilised and adequately supported. This will help prevent it from falling and causing injury to the operator or damage to the motorcycle.

1. Remove and discard the lower brake hose retaining clip, item 1 as shown in the illustration.



1. Lower brake hose retaining clip
2. Upper brake hose retaining clip
3. Front brake hose
4. ABS sensor cable

Circulation

Initial and date when read and return to central file holder

Service Manager	Parts Manager	Sales Manager	Workshop Supervisor	Technician 1	Technician 2