

Reference	SSM72693
Models	XF / X250
Title	Interior lights flicker, wipers operate when operating steering column
Category	Electrical
Last modified	09-May-2016 00:00:00
Symptom	203000 Basic Electrical
Content	<p><u>Note</u> Could affect any vehicle but more noticable on 15my Affects saloon and sportsbrake</p> <p><u>Issue</u> Interior lights flicker, wipers make a single stroke of the screen only when the steering column is moving.</p> <p><u>Cause</u> Power supply</p> <p><u>Action</u> Please do not replace any parts for this issue. Replacing the Front Junction Box will not resolve. Engineering are working on a resolution which will be communicated via a technical bulletin.</p> <p>To fully understand the level of customer dissatisfaction please submit an EPQR referencing this SSM number for any customers who have reported this issue to you.</p>