

TECHNICAL BULLETIN
Q637 UPS7716-4bNAS1
13 OCT 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 100-00

Update Prior to Sale: USA Battery Legal Label

AFFECTED VEHICLE RANGE:

Discovery Sport (LC)

Model Year: 2017
VIN: 639816
Assembly Plant: Solihull

MARKETS:

USA

CONDITION SUMMARY:

Situation: An issue has been identified on the one vehicle within the listed Affected Vehicle Range where a replacement battery has been fitted without the required USA legal label.

Action: Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

This program does not apply to any vehicle already registered and in use, either with the retailer or customer. Any vehicle already in use may continue to be driven and any repair instructions deemed necessary will be communicated through a separate Field Action or Technical Bulletin.

PARTS:



NOTE: Order only the expected percentage demand of parts identified.

| DESCRIPTION | PART No./SUNDRY CODE | QTY./VALUE | EXPECTED % of VEHICLES REQUIRING PARTS |
|---------------|----------------------|------------|--|
| Battery label | YGC500070 | 1 | 100 |

SPECIAL TOOLS:

Refer to Workshop Manual/Service Instruction for any required special tools

WARRANTY:



NOTE: Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code **Q637** together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **11 April 2017** closure date must be submitted or payment within 30 calendar days of completion of the repair.



Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIX to obtain the latest repair time.

| PROGRAM CODE | OPTION CODE | DESCRIPTION | SRO | TIME (HOURS) | PARTS/SUNDRY CODE | QTY./VALUE |
|--------------|-------------|---|----------------------|--------------|-------------------|------------|
| Q637 | A | Replace battery label | 05.10.10 | 0.10 | YGC500070 | 1 |
| Q637 | B | Replace battery label Drive in/drive out | 05.10.10 02.02.02 | 0.10 0.20 | YGC500070 - | 1 - |

Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1. Visually check if the battery warning label is installed as shown.
 - If the battery warning label is installed, release the vehicle.
 - If the battery warning label is not installed, install a new battery warning label as shown.



E198776