

TECHNICAL BULLETIN
Q620 UPS6716-6bNAS1
29 SEP 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 418-00

Update Prior to Sale: Missing Harness To Headlamp

AFFECTED VEHICLE RANGE:

Range Rover Evoque (LV)
Model Year: 2017
VIN: 171390
Assembly Plant: Halewood

MARKETS:

USA

CONDITION SUMMARY:

Situation: An issue has been identified on the vehicle within the listed Affected Vehicle Range where the wrong headlamp wiring harness has been fitted to the vehicle; consequently, the harness is missing supplementary relays and contains additional circuits. The daytime running lamps will not function on the vehicle.

Action: Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

PARTS:



NOTE: Order only the expected percentage demand of parts identified.



NOTE: The fuse box and engine compartment wiring harness assembly has been supplied direct to the retailer free of charge.

DESCRIPTION	PART No./SUNDRY CODE	QTY./VALUE	EXPECTED % of VEHICLES REQUIRING PARTS
Bolt	QYG500090	1	100

WARRANTY:



NOTE: Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code **Q620** together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **27 March 2017** closure date must be submitted or payment within 30 calendar days of completion of the repair.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE
Q620	B	Fuse box and engine compartment wiring harness assembly - renew	86.70.55	11.90	QYG500090	1
Q620	C	Fuse box and engine compartment wiring harness assembly - renew Drive in/drive out	86.70.55 02.02.02	11.90 0.20	QYG500090 -	1 -

Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1. Install the supplied engine harness (see TOPIx Workshop Manual section 418-00: Module Communications Network - Battery Junction Box (BJB) GTDi 2.0L Petrol).