

Reference	SSM72937
Models	Range Rover Evoque / L538
Title	L538c Range Rover Evoque Convertible Folding Top (Roof) reporting not locked
Category	Body
Last modified	19-Aug-2016 00:00:00
Symptom	105000 Roof Options

Content Issue: Customers are reporting that the folding Convertible Top (Roof) is not operating. They may also report an error message "Top is not locked, less than 50km/h drive".
This error has been observed during static position and whilst moving.

Cause: The folding Top (Roof) action is inhibited.

Action: The TOPIx workshop manual has now been updated with an initialization procedure to help resolve this issue. The following procedure re-calibrates the rear window operation.

Please refer to:

- TOPIx Workshop manual
- 501-18: Folding Top - Folding Top
- General Procedures
- Folding Top - Initialization