

---

<b>Reference</b>	SSM72940
<b>Models</b>	Discovery Sport / L550 Range Rover Evoque / L538
<b>Title</b>	Ambient air temperature sensor intermittent/inoperative or erratic readings
<b>Category</b>	Body
<b>Last modified</b>	26-Aug-2016 00:00:00
<b>Symptom</b>	103000 Mirrors
<b>Content</b>	<p><u>Issue:</u> Customers may report erratic ambient air temperature readings or default setting (i.e. -40 degrees).</p> <p><u>Cause:</u> Ambient air temperature sensor circuit signal fault.</p> <p><u>Action:</u> TOPIx has been updated for diagnosis and testing, please see:</p> <ul style="list-style-type: none"><li>• Workshop Manual</li><li>• 5: Body and Paint</li><li>• 501-09: Rear View Mirrors</li><li>• Diagnostic and testing</li><li>• Rear View Mirrors</li></ul>