

<b>Reference</b>	SSM72785
<b>Models</b>	F-PACE / X761
<b>Title</b>	X761 Suspension Creak Noise From Rear Of Vehicle
<b>Category</b>	Chassis
<b>Last modified</b>	23-May-2016 00:00:00
<b>Symptom</b>	304000 Suspension System
<b>Attachments</b>	Rear Spring Isolator.pdf (Rear Spring Isolator.pdf) Rear Spring Label.pdf (Rear Spring Label.pdf)
<b>Content</b>	<p>Issue: A vehicle user may report a creak noise appearing to come from the rear suspension of the vehicle.</p> <p>Cause: The rear suspension coil spring rubber isolator deforms allowing the coil spring to contact the body in white cone.</p> <p>Action: Please raise an ePQR detailing which side is exhibiting the issue; if possible also attach images showing any foul/touch conditions and the details of the parts label attached to the spring (as per attachment)</p> <p>No repair action to be undertaken. Engineering are aware of the concern and a further communication will be issued once a robust fix is identified.</p>



