

Reference	SSM72788
Models	F-PACE / X761
Title	F-Pace Glove Box rattle
Category	Body
Last modified	23-May-2016 00:00:00
Symptom	107000 Interior Trim
Attachments	FPace Glovebox Attachment.pdf (FPace Glovebox Attachment.pdf)
Content	<p>Issue: Customer may report a Rattle from the glove box area on F-Pace Vehicles</p> <p>Cause: No anti rattle tape fitted in specific areas</p> <p>Action: If anti rattle tape is not present, as in picture 2 & 3, apply anti rattle tape as per picture 4. Use anti rattle tape that is present in squeak and rattle tool kit</p>

