

Reference	SSM72790
Models	F-PACE / X761
Title	F Pace Front License Plate Plinth Does Not Fit Correctly
Category	Body
Last modified	26-May-2016 00:00:00
Symptom	108000 Ext. Trim/Accessories
Attachments	X761 Front plinth graphic (1).pdf (X761 Front plinth graphic (1).pdf)
Content	<p>Issue: The front license plate plinth does not fit on the bumper correctly</p> <p>Cause: The plinth has 2 locating pegs but no matching holes on the bumper (see attachment)</p> <p>Action: Remove the 2 locating pegs to allow correct fitting of the plinth, ensure they are flush with no sharp edges.</p>

