
Reference	SSM72811
Models	F-PACE / X761 XE / X760 XF / X260 XJ / X351
Title	InControl Touch Pro, unable to reset `Valet mode` using pin code
Category	Electrical
Last modified	15-Jun-2016 00:00:00
Symptom	207000 Entertainment Systems
Content	<p><u>Issue</u> The Touch Screen is inoperative with a Pop-up message 'Input the PIN Code'. It will also not be possible to open the luggage/tailgate and the Glove box.</p> <p><u>Cause</u> Mismatch of Master PIN Code Entered.</p> <p><u>Actions</u> This cannot be rectified by any actions via SDD, do not carryout a software update to the Infotainment Control Module(IMC) If you have this issue on a vehicle you are requested to contact Dealer Technical Support(DTS) by raising a Technical Assist(TA)</p>