

November 15, 2016

05247 Version 1

Product Update: 2017 Ridgeline Electric Trailer Brake Sub-Harness

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2017	Ridgeline	AWD	Check the iN VIN status for eligibility

BACKGROUND

During assembly, the electric trailer brake sub-harness was not placed in the vehicle glovebox. The owner's manual indicates this sub-harness is included with the vehicle and is used for trailers that have an electric brake. The missing sub-harness may cause confusion and potential customer dissatisfaction.

CUSTOMER NOTIFICATION

Owners of affected vehicles sold before November 14, 2016 will have the harness directly mailed to them.

Only vehicles shown as in dealer inventory as of November 14, 2016 are covered by this bulletin.

Do an iN VIN status inquiry to make sure the vehicle is shown as eligible.

Some vehicles affected by this campaign may be in your new or used vehicle inventory. Repair these vehicles before they are sold.

CORRECTIVE ACTION

Place an electric trailer brake sub-harness in the glovebox.

PARTS INFORMATION

Part Name	Part Number	Quantity
Electric Trailer Brake Sub-harness	06320-SZA-A00	1

WARRANTY CLAIM INFORMATION

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8231AE	Place an electric trailer brake sub-harness in the vehicle.	0.2 hr	6TE00	KC800	16-102A	74690-T6Z-A10

REPAIR PROCEDURE

Place an electric trailer brake sub-harness in the glovebox.

END

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.