

[Next Unread Message](#)[View Message](#)

Sent on 02 25 2016 Expires on 03 18 2016

From Motorcycle National Field Service

Subject SAFETY RECALL: 2014 NSS300/A, Service Bulletin Published



Motorcycle National Field Service

February 25, 2016

Service Bulletin: 2014 NSS300/A #2 - Rear Brake Line Joint Torque

Dear Honda Powersports Dealer:

The Service Bulletin in support of the SAFETY RECALL of 2014 NSS300/A scooters for a potentially loose rear brake line joint is posted on *IN*.

SERVICE BULLETIN

SAFETY RECALL: NSS300 #2 includes the affected models, repair procedure, parts information, as well as warranty claim information.

CUSTOMER NOTIFICATION

AHM intends to mail customer letters as early as possible, subject to State registration information..

PARTS INFORMATION

The repair procedure for this campaign does not require any parts..

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact Motorcycle TechLine at (800) 421-1900, Option 9; through *TechLine Connect* on *IN*; or contact your District Service Manager.

Sincerely,

American Honda Motor Co., Inc.**Bradley Little**Manager, National Field Service
Motorcycle Division

Bulletin Number: 16-0048