

Reference	SSM72737
Models	Range Rover / L405 Range Rover Sport / L494
Title	L405 Range Rover & L494 Sport. Seating, Lumbar / Massage Function & diagnostic's
Category	Body
Last modified	20-Apr-2016 00:00:00
Symptom	101000 Seating
Content	<p>Issue L405 Range Rover and L494 Range Rover Sport Sport Customers may report a concern with the Lumbar / Massage function, In particular 'Air Leaks' from the Lumbar / Massage function Cause The Lumbar / Massage solenoid block is fitted with an air exhaust valve that is designed to expel air under operating conditions. This is not an air leak and does not represent a solenoid block failure Action Technicians are advised that should a Customer report any concern with the Lumbar / Massage function, that they follow the newly released diagnostic's in Topix detailed under 501-10 A/B; Diagnosis & Testing; Seats - Vehicles with Lumbar / Massage</p>