

TECHNICAL BULLETIN  
Q538 UPS11515-1bNAS1  
07 JAN 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

**SECTION: 418-02**

Update Prior to Sale: Non-Business Seats Long Wheelbase 12V Auxiliary Socket

**AFFECTED VEHICLE RANGE:**

**Range Rover (LG)**

**Model Year:** 2016

**VIN:** 243639-252606

**Assembly Plant:** Solihull

**Cab style:** Long Wheelbase

**With:** Business Seats

**MARKETS:**

NAS

**CONDITION SUMMARY:**

**Situation:** An issue has been identified on a limited number of vehicles listed in the Affected Vehicle Range where the front center console rear cubby box 12V auxiliary socket is inoperative due to the main cabin harness missing power and ground circuits.

**Action:** Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

This UPS Notice does not apply to vehicles already registered and in use, either with the retailer or the customer. Any vehicle already in use may continue to be driven and any repair instructions deemed necessary will be communicated through a separate Technical Bulletin or Field Action.

**PARTS:**



**NOTE: when ordering parts, use the VIN of the affected vehicle and order only the expected percentage demand of parts identified.**

DESCRIPTION	PART No./SUNDRY CODE	QTY./VALUE	EXPECTED % of VEHICLES REQUIRING PARTS
Terminal Kit	LR083635	1	100

**SPECIAL TOOLS:**

Refer to Workshop Manual/Service Instruction for any required tools.

**WARRANTY:**



**NOTE: check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.**