

TECHNICAL BULLETIN  
Q554NAS1  
13 JAN 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

**SECTION: 204-04**

Service Action: Spare Wheel Lift Assist Strap Missing

**AFFECTED VEHICLE RANGE:**

**Range Rover Sport (LW)**

**Model Year:** 2016  
**VIN:** 630157-637941  
**Assembly Plant:** Solihull

**Range Rover Sport (LW)**

**Model Year:** 2016  
**VIN:** 542189-560184  
**Assembly Plant:** Solihull

**MARKETS:**

NAS

**CONDITION SUMMARY:**

**Situation:** An issue has been identified on a limited number of 2016 model year Range Rover Sport (L494) vehicles, fitted with 21" wheels and a full-size spare wheel, where the spare wheel lift assist strap is missing from the vehicle.

**Action:** Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

**PARTS:**



**NOTE: when ordering parts, order only the expected percentage demand of parts identified.**

DESCRIPTION	PART No./SUNDRY CODE	QTY./VALUE	EXPECTED % of VEHICLES REQUIRING PARTS
Spare wheel lift assist strap	LR057367	1	100

**SPECIAL TOOLS:**

No special tools required.

**WARRANTY:**

 **NOTE: check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.**

At the time of confirming a booking for vehicle repair, ensure that all outstanding Field Action programs are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code **Q554** together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **31 January 2018** closure date must be submitted or payment within 30 calendar days of completion of the repair.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.


PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE
Q554	B	Place the spare wheel lift assist strap next to the spare wheel	05.10.10	0.10	LR057367	1
Q554	C	Place the spare wheel lift assist strap next to the spare wheel Drive in/drive out	05.10.10 02.02.02	0.10 0.20	LR057367 -	1 -

Normal Warranty policies and procedures apply.

### **SERVICE INSTRUCTION:**

**1**Open the tailgate.

**2**Lift the spare wheel cover.



**3**Place the spare wheel lift assist strap next to the spare wheel.

**4**Lower the spare wheel cover.

**5**Close the tailgate.