Reference	SSM72628
Models	Discovery Sport / L550
Title	L550 Discovery Sport Abnormal Door Speaker Sound
Category	Electrical
Last modified	08-Feb-2016 00:00:00
Symptom	207000 Entertainment Systems
Content	Issue:
	The eventual area of the tibere is a liberties bound and her absorbed from a

The customer may report that there is a vibration, buzz or other abnormal noise from a door speaker.

## Cause:

Under investigation.

## Action:

On confirmation of the problem:

- · Ensure that all door trims and fixings are secure.
- · Check that the speaker is mounted securely and properly connected.
- · Make sure that no other parts are loose within the door.

If the problem persists:

- · Raise an EPQR explaining the issue and work carried out.
- · Await a response before replacing any parts.