
Reference	SSM72632
Models	Range Rover Evoque / L538
Title	L538 - Loadspace Cover and Inner Tailgate Wear
Category	Body
Last modified	15-Feb-2016 00:00:00
Symptom	107000 Interior Trim

Content**Issue:**

Customers report wear to the loadspace cover and tailgate trim due to the parts fouling.

Cause:

If the loadspace cover is located outside of the designated retention lugs, a foul condition can exist between the edges of the loadspace cover and the tailgate inner trim panel, causing visible wear to both parts.

Action:

Confirm the issue and refer to LTB00507v2.

Range Rover Evoque (LV)

Model Year: 2012-2013

VIN: H000001-H856579

If the vehicle falls within the affected VIN range:

- Carry out bulletin LTB507v2.
- Make the parts available for return through the usual warranty channels.

If the vehicle falls outside of the specified Affected Vehicle Range:

- Do NOT carry out bulletin LTB507v2.
- Raise an EPQR, attaching images of the loadspace cover and damage to the inner tailgate.
- Await further instructions before carrying out any repairs.