
Reference	SSM72636
Models	Discovery Sport / L550 Range Rover Evoque / L538
Title	L550 & L538 Climate Controlled Seat Diagnostics
Category	Body
Last modified	22-Feb-2016 00:00:00
Symptom	101000 Seating

Content**Issue:**

Any issue affecting the operation of Climate Control Seats. For example:

- Seat heating or cooling inoperative
- Intermittent operation.
- Noisy operation.
- Poor heating or cooling efficiency.
- Heating or cooling operation slow.

Cause:

Under investigation.

Action:

- Refer to the Diagnosis and Testing section of "501-10: Seating" of the Workshop Manual and follow the information within "Seats – Vehicles With: Climate Controlled Seats".
- Use the information supplied as a guide to finding root cause of the fault.

- Confirm repair through EPQR.
- Request assistance through TA if unable to resolve.