

<b>Reference</b>	SSM72675
<b>Models</b>	LR4 / L319 Range Rover / L322 Range Rover Sport / L494
<b>Title</b>	Remote Key Fob Material Adrift
<b>Category</b>	Electrical
<b>Last modified</b>	29-Feb-2016 00:00:00
<b>Symptom</b>	205000 Electrical Accessories
<b>Attachments</b>	Remote Key Fob Date Code.pdf (Remote Key Fob Date Code.pdf)
<b>Content</b>	<p><b>Issue:</b> A customer may report that the remote key fob material appears to be peeling away from the remote and requires replacement.</p> <p><b>Cause:</b> Currently under analysis.</p> <p><b>Action:</b> Replace the remote key fob and submit an ePQR and photograph of the date code attached to the inside of the old remote (please see attachment). ePQRS only required for vehicles within the VIN range below:</p> <p>Range Rover – EA178750 onwards</p> <p>Range Rover Sport – EA381017 onwards</p> <p>Discovery 4/ LR4 – EA724953 onwards</p>