

---

<b>Reference</b>	SSM72781
<b>Models</b>	Range Rover Evoque / L538
<b>Title</b>	L538 Range Rover Evoque 16MY bonnet latch issues
<b>Category</b>	Body
<b>Last modified</b>	17-May-2016 00:00:00
<b>Symptom</b>	112000 Latches/Locks & Security

---

**Content**      Issue: Customers are reporting bonnet latch issues such as bonnets hard to latch or, the Instrument Panel showing bonnet not latched warning.

Cause: Retailers are adjusting the bonnet latch position to rectify.

Action:

All retailers please raise an EPQR.

UK retailers also contact Ian Cavanagh [icavanag@jaguarlandrover.com](mailto:icavanag@jaguarlandrover.com) to report Range Rover Evoque (16MY onwards) bonnet latching issues as JLR would like to visit vehicles in a failed state.