

# TECHNICAL BULLETIN

## LTB00920NAS2

### 27 JUN 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

**This reissue replaces all previous versions. Please destroy all previous versions.**

### **SECTION: 501-12**

## Lower Glovebox Damper Inoperative

### **AFFECTED VEHICLE RANGE:**

#### **Range Rover Sport (LW)**

**Model Year:** 2014-2016  
**VIN:** 001154-567200  
**Assembly Plant:** Solihull

#### **Range Rover Sport (LW)**

**Model Year:** 2015-2016  
**VIN:** 600009-645528  
**Assembly Plant:** Solihull

#### **Range Rover (LG)**

**Model Year:** 2013-2016  
**VIN:** 001204-269049  
**Assembly Plant:** Solihull

MARKETS:

NAS

### **CONDITION SUMMARY:**

**Situation:** The lower glovebox may open quicker than expected.

**Cause:** This may be caused by an incorrect gear pitch in damping mechanism.

**Action:** Should a customer express this concern, follow the Service Instruction below.

### **PARTS:**

LR084595	Glovebox Lower Lid - LHD - Leather Ebony	1
LR084597	Glovebox Lower Lid - LHD - Leather Almond	1
LR084596	Glovebox Lower Lid - LHD - Leather New Tan	1
LR084590	Glovebox Lower Lid - LHD - Leatherette Almond	1
LR084591	Glovebox Lower Lid - LHD - Leather Pimento/Red	1
LR084592	Glovebox Lower Lid - LHD - Leather Lunar	1
LR084587	Glovebox Lower Lid - LHD - Leatherette Cirrus	1
LR084588	Glovebox Lower Lid - LHD - Leatherette Ivory	1
LR084589	Glovebox Lower Lid - LHD - Leatherette Ebony	1
LR084593	Glovebox Lower Lid - LHD - Leather Cirrus	1
LR084594	Glovebox Lower Lid - LHD - Leather Ivory	1

LR084599

Glovebox Housing - LHD

1

**WARRANTY:**

 **NOTE:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

 **NOTE:** DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Lower Glovebox - Renew - Range Rover (L494)	<b>76.52.03</b>	1.0	42	LR060005
Lower Glovebox - Renew - Range Rover (L405)	<b>76.52.03</b>	0.8	42	LR060005

 **NOTE:** Normal Warranty procedures apply.

**SERVICE INSTRUCTION:**

1. Install a new lower glovebox (see TOPIx Workshop Manual, section 501-12: Instrument Panel and Console - Glove Compartment).