Reference	SSM71118
Models	Range Rover / L405
	Range Rover Sport / L494
Title	Range Rover (LG) & Range Rover Sport (LW) Towing eye Cover fitment
Category	Body
Last modified	08-Jul-2016 00:00:00
Symptom	108000 Ext. Trim/Accessories
Content	Issue
	Front towing eye cover is loose / incorrectly fitted
	Cause
	Incorrect installation by the retailer or customer
	Action
	The tow eye cover installation process has been updated; a retailer or customer can access the information through one of the following:-
	Topix - PDI manual
	Topix – Select Vehicle and Model Year – Documents – WSM - 1: General information;
	101: Pre-delivery information; 101-01A: Pre-delivery inspection manual Description and
	Operation. Refer to Vehicle Exterior, Step 26 / 26.1 (LG) or 25.1 (LW).
	Land Rover Website
	Goto http://www.ownerinfo.landrover.com/ - Select Vehicle / Model Year – Vehicle
	Recovery – Front Towing Eye.