

Reference	SSM72883
Models	Discovery Sport / L550 Range Rover Evoque / L538
Title	InControl Touch Pro features make not function as expected(additional updates)
Category	Electrical
Last modified	18-Jul-2016 00:00:00
Symptom	207000 Entertainment Systems

Content**Applicable vehicles fitted with InControl Touch Pro**

Evoque Convertible from vin 137551

Discovery Sport from vin 633943

NOTE: Please note these are the main issues listed below. There are others that are not listed.

Issue

A customer may express a concern that the InControl Touch Pro features may not function as expected.

This includes

CD player performance.

Screen reset issues

Not be able to use the hard key to go to previous track, have to use the soft key or steering wheel key to complete the action

Voice command repeated twice.

Missing audio for FM after startup, recovered after source change.

Phone issues

Cause

Software

Action

Update the software for the Infotainment Control Module(IMC) with SDD 146.03 and NGI 001.00

The SRO for this is 86.91.13