

Bulletin No.: PIE0372

Date: 20-Jul-2016

Service Bulletin

INFORMATION

Subject: Engineering Information – Vehicle is Difficult to Shift or Will Not Shift Into Gear

Models: 2016 Chevrolet Cruze

Equipped with Manual Transmission (RPO M32)

Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is

listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the El does not show in GWM/IVH, disregard the Pl and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version

of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

Condition

Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this El.

Some customers may comment that it is difficult to shift the vehicle into gear and/or the vehicle will not shift into gear at all.

Cause

GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair tha may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

Instructions

If you encounter a vehicle with the above concern, contact one of the engineers listed below before attempting any repairs.

Contact Information

Engineer Name	Phone Number	
Steven Field	810-625-9931	
Steve Zeigler	248-255-7027	

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
8480498*	Engineering Information — Vehicle Difficult or Will Not Shift Into Gear Engineer Call	0.4 hr
*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

