

Service Bulletin

File in Section:

Bulletin No.: 16-NA-236

Date: July, 2016

TECHNICAL

Subject: OnStar Turn by Turn Volume Loud after Performing 17130 or 45340 Radio Reprogramming

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Branu.	wiodei.	from	to	from	to		
Chevrolet	Spark	2013	2014			All	All

Involved Region or Country	North America		
Additional Options (RPO)	Equipped with Bring Your Own Media (RPO UF7)		
Condition	Some customers may comment that their OnStar Turn by Turn volume is stuck high ever since having their radio reprogrammed as outlined in field action 17130 or 45340. Important: This only affects vehicles that were reprogrammed prior to July 13, 2016.		
Cause	This may be a result of the audio calibration volume being set to 45 instead of 20.		

Correction

If you encounter a vehicle with the above concern, SPS program the radio again and re-evaluate the concern. Refer to *Radio Programming and Setup* in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810335	Radio Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	

