Mazda North American Operations Irvine, CA 92618-2922



© 2017 Mazda Motor of America, Inc.

Subject: MAZDA RADAR CRUISE CONTROL (MRCC) WILL NOT SET	M-Tips No.: MT-005/17
	Last Issued: 03/27/2017

DESCRIPTION

APPLICABLE MODEL(S)/VINS

2017 CX-5 vehicles equipped with MRCC 2016-2017 CX-9 vehicles equipped with MRCC 2017 Mazda3 vehicles equipped with MRCC

Some vehicles equipped with Mazda Radar Cruise Control (MRCC) will not set (the system stays on standby) if the driver's seat belt is not fastened. This is a normal condition. Do not perform any repairs for this condition.



Seat Belt Warning Light

Remind the customer that they should always wear their seat belt and inform them that wearing the driver's seat belt will address this issue.

Page 1 of 1

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2017 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to <u>mtips@mazdausa.com</u>. All contributions become property of MNAO, which assumes permission to publish them without further consideration.