

ACURA Tech Line Summary Article

February 2017 BTS 170202 Version 1

EVAP System Leak from the Filler Neck? Don't Replace the Fuel Fill Pipe!

AFFECTED VEHICLES

2017 MDX and 2017 NSX

If there's an EVAP system leak from the filler neck (DTC P0455 [EVAP system large leak detected] or P0456 [EVAP system very small leak detected] is set), don't replace the fuel fill pipe! Instead, replace the mis-fuel inhibit device and the main flap unit. Acura parts stock carries replacement parts just for this purpose.

For replacement procedures, refer to the service information.

© 2017 American Honda Motor Co., Inc. - All Rights Reserved