

[Next Unread Message](#)[View Message](#)

Sent on	03	23	2017	Expires on	04	06	2017
---------	----	----	------	------------	----	----	------

From	Parts and Service Division
------	----------------------------

Subject	Request for Parts: 2017 CR-V MIL On with DTC P2583-76 Stored
---------	--

**PRIORITY/ACTION REQUIRED**

To: All Honda Service Managers/Advisors  
From: Technical Research & Support Group  
RE: Request for Parts: 2017 CR-V MIL On with DTC P2583-76 Stored

This message is solely directed to Honda dealership personnel; please handle accordingly.  
Print this iV message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda (AHM) is investigating certain 2017 CR-Vs with a customer complaint of the Malfunction Indicator Lamp (MIL) On with DTC P2583-76 (Temporary Stop of Integrated Driver Support System [Misalignment Millimeter Wave Radar]) Stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirement:

1. EX & Touring only.
2. Must have DTC P2583-76 stored.
3. No attempt has been made to re-aim the millimeter wave radar.

**Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.