

April 2017 This notice applies to your vehicle:

RE: 2015 Fit

Dear

What is the reason for this notice?

Our records indicate that a PRODUCT UPDATE has not been completed on this vehicle; refer to the address card for the affected VIN. A non-galvanized door handle bracket located inside each door was installed during manufacturing and may be susceptible to corrosion.

What will Honda do?

Please contact any authorized Honda dealer for an appointment to replace each door handle bracket and remove any corrosion found from the door handle areas. This work will be done free of charge.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact Honda Automobile Customer Service at 1-888-234-2138. You may also find this information at www.Hondacars.com.

We apologize for any inconvenience this product update may cause you.

Sincerely,

American Honda Motor Co., Inc. Honda Automobile Division