

DTC U1291-00 Falsely Set After Removing the No. 18 BACKUP (10 A) Fuse for Shipping

AFFECTED VEHICLES

2018 Odyssey

On early production vehicles, when the factory removed the No. 18 BACKUP (10 A) fuse for shipping, DTC U1291-00 (lost communication with the relay control module) was falsely set. This DTC doesn't cause any indicators to come on, but it will show up the first time you run an all DTC check with the i-HDS.

If you've got an early production vehicle with this DTC, just clear the DTC. If it doesn't come back, there's nothing more you need to do.

The factory will be applying a fix to keep this DTC from setting when it removes the backup fuse for shipping.